



## **MARINE SAFETY ALERT**

### **Inspections and Compliance Directorate**

February 21, 2025  
Washington, DC

Safety Alert 05-25-CH1

## **IMPORTANCE OF ADHERING TO HOT WORK PROCEDURES & IMPLEMENTING ROBUST LOCKOUT/TAGOUT PROGRAMS**

A recent marine casualty, resulting in a fire and severe injuries to two crewmembers, highlights the risks associated with Liquefied Natural Gas (LNG), performing hot work in hazardous zones, and the necessity of maintaining a robust lockout/tagout program.

The Coast Guard's investigation revealed that two crewmembers were conducting hot work in a known hazardous zone on the air castle deck of a tri-fueled vessel (LNG, diesel, battery). The hot work was being conducted in an area that should have been avoided as the vessel was using LNG as a fuel source at the time. Coast Guard investigators suspect that a malfunctioning actuator for the engines' purge valve subsequently vented methane vapors into the hot work area. Unaware of the vapors, a crewmember struck a lighter, igniting the methane and resulting in severe burns and a fire onboard.



Figure 1. Example lockout/tagout equipment




Figure 2. Image of fire on air castle deck

The International Code of Safety For Ships Using Gases or Other Low-Flashpoint Fuels (IGF Code) section 18.7.1 requires *“Hot work in the vicinity of fuel tanks, fuel piping and insulation systems that may be flammable, contaminated with hydrocarbons, or that may give off toxic fumes as a product of combustion shall only be undertaken after the area has been secured and proven safe for hot work and all approvals have been obtained.”* Although the IGF Code was not specifically applicable to this vessel at the time of the incident, it is highly recommended that this prescriptive requirement be taken into consideration on all vessel's operating with LNG as a fuel source. The crewmembers in this incident performed hot work in the area without applying lockout/tagout procedures, as described in the IGF Code.

The Coast Guard **strongly recommends** that vessel owners, operators, and other stakeholders:

- **Review and Implement Lockout/Tagout Procedures.** Ensure LNG systems are tagged out before conducting any hot work in or near hazardous areas. Crewmembers must verify the lockout/tagout status of the system before beginning work.

- **Develop Multi-Fuel System Procedures.** Establish procedures to ensure all crewmembers are aware of the additional hazards posed by multi-fuel systems, with a clear focus on what work is permissible based on the active fuel type.

Marine inspectors, investigators, and surveyors are urged to remain vigilant about these issues and take corrective actions as needed.

This Safety Alert is provided for informational purposes only and does not relieve any domestic or international safety, operational, or material requirement. Developed by Marine Safety Unit Houma and distributed by the Office of Investigations and Casualty Analysis. Questions may be sent to [HQS-SMB-CG-INV@uscg.mil](mailto:HQS-SMB-CG-INV@uscg.mil).