

Ship Name: **PACIFIC WORLD**

Ship Type: **Passenger Ship**

Flag: **Panama**

IMO Number: **9000259**

Date of Action: **7/11/2023**

Action Taken: **Detention**

Port: **Honolulu, Hawaii**

Unit: **Sector Honolulu**

Recognized Org: **Lloyd's Register**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Class Related**

Relevant Certificates: **Passenger Ship Safety**

Organization Related
to Detention: **Lloyd's Register**

Ship Management: Owners, Operators, or Managers
PACIFIC WORLD CRUISE LIMITED
INTEGRATED CRUISE MANAGEMENT
PTE. LTD.

Deficiencies: Code - Category

11104 - Rescue boats

11101 - Lifeboats

Description

Before the ship leaves port and at all times during the voyage, all life-saving appliances shall be in working order and ready for immediate use. Port side fast rescue boat engine control signals were not being received by the engine rendering the fast rescue boat unable to maneuver.

Before the ship leaves port and at all times during the voyage, all life-saving appliances shall be in working order and ready for immediate use. Lifeboat #2 engine overheated due to the engine cooling system not operating properly. This prevented lifeboat #2 from returning to the mothership under its own power and forced an emergency mooring to the pier, aft of the mothership. Lifeboat #7 reduction gear would not clutch ahead. Lifeboat Tender #1 reduction gear would not clutch in.