

Ship Name: **MSC VITTORIA**

Recognized Org: **DNV**

Ship Type: **Containership**

Recognized Security  
Organization (RSO):

Flag: **Panama**

Recognized Org  
(RO) Related: **Not Class Related**

IMO Number: **9299551**

Relevant Certificates:

Date of Action: **8/9/2023**

Action Taken: **Detention**

Organization Related  
to Detention:

Port: **Portsmouth, Virginia**

Unit: **Sector Virginia**

Ship Management: Owners, Operators, or Managers  
**Compania Naviera Vittoria S.A.**  
**Mediterranean Shipping Co. s.r.l**

Charterers  
**MSC Mediterranean Shipping Company  
S.A.**

Deficiencies: Code - Category

Description

**15102 - Company responsibility and  
authority**

**The company and the ship shall comply with the requirements of the ISM Code. The company should establish procedures to ensure that the ship is maintained in conformity with the provisions of the relevant rules and regulations. The company should ensure: appropriate corrective action is taken. PSCO observed, during an expanded exam, the following: Failure of the company and ship to properly manage failing E/R equipment, to include: A/E fuel delivery, A/E cooling water, oil mist detectors on A/E, steam pipes, fuel oil booster pumps, piping for OWS, piping for BWMS, E/R ventilation, F/O leak alarm on A/E. External ISM audit required prior to being released from detention. 74SOLAS(20) IX/3.1 ISM code 10 30ABC**

**07126 - Oil accumulation in engine  
room**

**Means shall be provided to control leaks of flammable liquids. PSCO observed leaking F/O booster pump in purifier space.**

**07126 - Oil accumulation in engine  
room**

**Means shall be provided to control leaks of flammable liquids. PSCO observed A/E #04 leaking fuel and lube oil from cylinder tops.**