Ship Name: JAUME II Recognized Org: RINA Services S.p.A.

Ship Type: Passenger Ship

Recognized Security

Organization (PSO):

Flag: Cyprus Organization (RSO):

IMO Number: 9116113

Recognized Org
(RO) Related: Not Class Related

Date of Action: 1/30/2024 Relevant Certificates:

Action Taken: **Detention** 

Port: **Miami, Florida**Organization Related to Detention:

Unit: Sector Miami

Ship Management: Owners, Operators, or Managers

Balearia Eurolineas Maritimas SA

Charterers

**Kanalion Marine Company Limited** 

Deficiencies: Code - Category

15109 - Maintenance of the ship and

equipment

Description

The company and the ship shall comply with the requirements of the international safety management code. For the purpose of this regulation, the requirements of the code shall be treated as mandatory. The company should establish procedures to ensure that the ship is maintained in conformity with the provisions of the relevant rules and regulations and with any additional requirements which may be established by the company.

The nature of the below deficiencies provides objective evidence of a serious failure of the implementation of the ISM code. An external ISM audit report, satisfactory to the Coast Guard must be submitted prior to the clearance of this deficiency and departure.

06104 - Lashing material

Cargo, cargo units and cargo transport units carried on or under deck shall be so loaded, stowed and secured as to prevent as far as practicable throughout the voyage, damage or hazard to the ship and the persons on board, and loss of cargo overboard.

Approximately 15% of the total D-rings to secure vehicles to the deck are missing. Vessel's monthly maintenance logs for the cargo securing equipment and maintenance checklist was unavailable for the lashing devices and lashing points.

01108 - Load Lines (including Exemption)

The International Load Line Certificate shall not be delivered to the ship until the officer or surveyor acting under the provisions of article 13 of the present convention has certified that the marks are correctly and permanently indicated on the ships side.

The vessels load line did not match the load line certificate to include; classification society was incorrect and load line markings were not properly marked.