

Ship Name: **SUBSEA RESPONDER II**

Ship Type: **Supply Ship**

Flag: **Marshall Islands**

IMO Number: **9225495**

Date of Action: **9/4/2024**

Action Taken: **Detention**

Port: **Port Arthur, Texas**

Unit: **Marine Safety Unit Port Arthur**

Recognized Org: **American Bureau of Shipping**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers

Hydra Ops LLC

Subsea Responder II LLC

Deficiencies: Code - Category

**04114 - Emergency source of power -
Emergency generato**

Description

The electrical power available shall be sufficient to supply all those services that are essential for safety in an emergency, due regard being paid to such services as may have to be operated simultaneously.

Vessel's Chief Engineer stated there was a jacket water leak on the number 2 cylinder, a possible crack in the cylinder liner. Did not want to start the engine to avoid a possible engine failure.

15106 - Shipboard operations

The company should establish procedures to ensure the ship is maintained in conformity with the provisions of the relevant rules and regulations. The vessel's crew was unable to provide SMS procedures upon request and were unfamiliar with the vessel's Safety Management System. Based on this and the technical and operational nature of the deficiencies noted below provide objective evidence of a serious failure of implementation of the ISM code. An additional external verification is required to be carried out by the RO (ABS) prior to the vessel's departure from port.