

Ship Name: **MSC JOANNA**

Ship Type: **Containership**

Flag: **Panama**

IMO Number: **9304435**

Date of Action: **1/5/2023**

Action Taken: **Detention**

Port: **Charleston, South Carolina**

Unit: **Sector Charleston**

Recognized Org: **Det Norske Veritas**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers

D & C Marine LTD

Mediterranean Shipping Co. s.r.l

Mediterranean Shipping Co. s.r.l

Charterers

Mediterranean Shipping Company, S.A.

Deficiencies: Code - Category

15109 - Maintenance of the ship and equipment

11101 - Lifeboats

15110 - Documentation-ISM

Description

The safety management system should ensure compliance with mandatory rules and regulations; and that applicable codes, guidelines and standards recommended by the Organization, Administrations, classification societies and maritime industry organizations are taken into account. The combination of deficiencies below indicates a serious failure, or lack of effectiveness, of the implementation of the ISM Code. A safety management audit shall be carried out by the Administration or the RO before the ship may be released from detention.

Life-saving appliances shall be in working order and ready for immediate use. PSCO observed STBD lifeboat/rescue boat failed to engage propulsion during operational test. Upon further examination, the lifeboat's gearbox bolts attaching it to drive shaft were sheared. (ISM Related)

The fire detection and fire alarm systems shall be kept in good order so as to ensure their required performance if a fire occurs. PSCO observed the fire detection panel in the bridge was in fault status and could not be cleared. (ISM Related)