

Ship Name: **NAVIOS DOMINO**

Ship Type: **Containership**

Flag: **Marshall Islands**

IMO Number: **9478494**

Date of Action: **5/31/2023**

Action Taken: **Detention**

Port: **Norfolk, Virginia**

Unit: **Sector Virginia**

Recognized Org: **DNV**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers
Navios Container Management Inc
Jiahai International Ship Lease Co. Ltd

Charterers
Hapag Lloyd

Deficiencies: Code - Category

**15102 - Company responsibility and
authority**

**07126 - Oil accumulation in engine
room**

Description

The company and the ship shall comply with the requirements of the ISM Code. The company should establish procedures to ensure that the ship is maintained in conformity with the provisions of the relevant rules and regulations. The company should ensure; appropriate corrective action is taken. PSCO observed, during an expanded exam the following: Failure of the company and ship to properly manage failing E/R equipment, to include, M/E cooling water system, M/E F/O lines, hydraulic pump cooling system, and boiler. An external ISM audit is required prior to release from the detention.

Means shall be provided to control leaks of flammable liquids. PSCO observed excessive leakage of F/O in several locations on the M/E fuel return lines and oil soaked lagging, as well as diesel fuel spraying from the pressure gauge on the diesel fuel line.