Ship Name: **PORTO LEONE**

Ship Type: Bulk Carrier

Flag: Panama

IMO Number: 9656096

Date of Action: 8/30/2023 Action Taken: **Detention**

Port: Staten Island, New York

Unit: Sector New York

Recognized Org: Lloyd's Register

Recognized Security Organization (RSO):

Recognized Org Not Class Related

Relevant Certificates:

Organization Related

to Detention:

Ship Management: Owners, Operators, or Managers

Uniteam Marine Shipping GmbH

Porto Leone Shipping Co.

Charterers Bunge S.A.

Deficiencies: Code - Category

> 15109 - Maintenance of the ship and equipment

Description

The company should establish procedures to ensure that the ship is maintained in conformity with the provisions of the relevant rules and regulations and with any additional requirements which may be established by the company. In meeting these requirements, the company should ensure that... any non-conformity is reported with its possible cause, if known, and appropriate corrective action is taken. PSCOs collected objective evidence including fuel oil leaks on all three ships service generators, multiple oily rags and deteriorating lagging throughout the engine room, the emergency hydraulic reserve tank was less than 50% capacity as indicated by the ship's SMS, both steering pumps are actively leaking hydraulic fluid, and that the vessel was not identifying non-conformities and following the inspection and reporting requirements of its SMS. An external audit conducted by a third party is required.

07126 - Oil accumulation in engine room

Means shall be provided to control leaks of flammable liquids. All ships service generators found actively leaking fuel oil. PSCOs observed standing oil behind the number five main engine cylinder and excessive oil in the bilge.

07126 - Oil accumulation in engine room

Means shall be provided to restrict the ignitability of combustible material. PSCOs observed multiple oilsoaked rags throughout the engine room as well as oilsoaked and deteriorating lagging.