

Ship Name: **PEPIN EXPRESS**

Recognized Org: **Conarina**

Ship Type: **General Dry Cargo Ship**

Recognized Security
Organization (RSO):

Flag: **Tanzania**

Recognized Org
(RO) Related: **Not Class Related**

IMO Number: **9196228**

Relevant Certificates:

Date of Action: **9/11/2023**

Action Taken: **Detention**

Organization Related
to Detention:

Port: **Miami, Florida**

Unit: **Sector Miami**

Ship Management: Owners, Operators, or Managers

Americas Marine Management Services, Inc.

Trans Pepin S de RL

Deficiencies: Code - Category

Description

15105 - Resources and personnel

The company and the ship shall comply with the requirements of the International Safety Management Code. For the purpose of this regulation, the requirements of the Code shall be treated as mandatory. The company should establish procedures to ensure that the ship is maintained in conformity with the provisions of the relevant rules and regulations and with any additional requirements which may be established by the company. In meeting these requirements, the company should ensure that any non-conformity is reported, with its possible cause, if known. The nature of the below deficiencies provides objective evidence of a serious failure of the implementation of the ISM Code. An external ISM audit report, satisfactory to the Coast Guard, must be submitted prior to clearance of this deficiency and departure.

01212 - Certificate for medical care

Each seafarer holding a certificate issued under the provisions of the Convention, who is serving at sea, shall also hold a medical certificate issued in accordance with the provisions of this regulation and of section A-1/9 of the STCW Code. PSCO's discovered that the medical certificate for the Chief Engineer was expired.