

Ship Name: **FUJI BAY**

Ship Type: **General Dry Cargo Ship**

Flag: **Liberia**

IMO Number: **8920141**

Date of Action: **10/2/2023**

Action Taken: **Detention**

Port: **Port Canaveral, Florida**

Unit: **MSD PORT CANAVERAL**

Recognized Org: **Lloyd's Register**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers

Seatrade Groningen B.V.

FUJI BAY SHIPPING COMPANY N.V

Deficiencies: Code - Category

**07110 - Fire fighting equipment and
appliances**

**04114 - Emergency source of power -
Emergency generato**

Description

The function of the detection system shall be periodically tested to the satisfaction of the Administration by means of equipment producing hot air at the appropriate temperature. Vessel was found to be using an open flame torch to test heat detectors, which contradicted SMS procedures and manufacturer instruction and may have damaged vital fire detection equipment rendering it incapable of detecting a fire.

Oil fuel pipes, which if damaged, would allow oil to escape from a storage, settling or daily service tank having a capacity of 500 L and above situated above the double bottom, shall be fitted with a cock or valve directly on the tank capable of being closed from a safe position outside the space. The quick closing line handle that is located outside of the EDG space broke during testing not allowing the generator to be shut off remotely in case of fire.