

Ship Name: **SANTA MARIA XPRESS**

Ship Type: **General Dry Cargo Ship**

Flag: **Togo**

IMO Number: **8926626**

Date of Action: **3/8/2024**

Action Taken: **Detention**

Port: **Miami, Florida**

Unit: **Sector Miami**

Recognized Org: **CONARINA**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Class Related**

Relevant Certificates: **International Load Line Certificate**

Organization Related
to Detention: **CONARINA**

Ship Management: Owners, Operators, or Managers
Dauids Sons Logistics LLC

Deficiencies: Code - Category

03108 - Ventilators, air pipes, casings

Description

Where air pipes to ballast and other tanks extend above the freeboard or superstructure decks, the exposed parts of the pipes shall be of substantial construction. PSCOs observed a 2" hole on the starboard side cargo airpipe located next to the bridge. PSCOs also observed a .5" hole on the starboard cargo air pipe on the main deck and a 2" hole on the waste oil pipe on the starboard side.