

Ship Name: **MSC PETRA**

Ship Type: **Containership**

Flag: **Liberia**

IMO Number: **9222302**

Date of Action: **5/21/2024**

Action Taken: **Detention**

Port: **Newark, New Jersey**

Unit: **Sector New York**

Recognized Org: **Bureau Veritas**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers
MSC Shipmanagement Ltd
Diaporos Oceanways Limited

Deficiencies: Code - Category

**15109 - Maintenance of the ship and
equipment**

**07126 - Oil accumulation in engine
room**

09209 - Electrical

Description

The company should establish procedures to ensure that the ship is maintained in conformity with the provisions of the relevant rules and regulations established by the company. The technical and/or operational nature of the deficiencies noted below provide objective evidence of a serious failure of the implementation of the ISM Code. An external audit report satisfactory to the COTP must be submitted prior to the clearance of this deficiency.

In a ship in which oil fuel is used, the arrangements for the storage, distribution and utilization of the oil fuel shall be as such to ensure the safety of the ship and persons on board. PSCO observed evidence of oil leakage from the space above the purifier room, which includes auxiliary engine #3.

Electrical installations shall be such that: the safety of passengers, crew and ship from electrical hazards will be ensured. PSCO observed water accumulation around switchboards in both port and starboard emergency escape routes from the engine room.