

Ship Name: **THOR INFINITY**

Ship Type: **Bulk Carrier**

Flag: **Singapore**

IMO Number: **9238466**

Date of Action: **5/1/2024**

Action Taken: **Detention**

Port: **New Orleans, Louisiana**

Unit: **Sector New Orleans**

Recognized Org: **Nippon Kaiji Kyokai**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers

Thoresen & Co (Bangkok) Ltd

Thoresen Shipping Singapore Pte Ltd

Deficiencies: Code - Category

**07108 - Ready availability of fire
fighting equipment**

**07110 - Fire fighting equipment and
appliances**

**15109 - Maintenance of the ship and
equipment**

Description

The firefighters outfits or sets of personal equipment shall be kept ready for use in an easily accessible location that is permanently and clearly marked. PSCO observed #2 firefighters outfit's SCBA bottle, located in the fire control room, empty and not ready for use.

Two spare charges shall be provided for each required breathing apparatus. Vessel is required to have 02 breathing apparatuses for a total of 06 charged SCBA bottles; PSCO observed only 05 charged SCBA bottles.

The company and the ship shall comply with the requirements of the International Safety Management Code. The company should establish procedures to ensure that the ship is maintained in conformity with the provisions of the relevant rules and regulations and with any additional requirements which may be established by the Company. The technical and/or operational nature of the deficiencies 01 and 02 provide objective evidence of a serious failure of the implementation of the ISM Code. An external audit report satisfactory to the OCMI must be submitted prior to clearance of this deficiency.