

Ship Name: **ASIAN SPIRIT**

Ship Type: **General Dry Cargo Ship**

Flag: **Liberia**

IMO Number: **9273806**

Date of Action: **11/20/2024**

Action Taken: **Detention**

Port: **Newark, New Jersey**

Unit: **Sector New York**

Recognized Org: **American Bureau of Shipping**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers

**Zhoushan Jianyang International Shipping
Management Co Ltd**

YWL Shipping Co Ltd

Deficiencies: Code - Category

**07123 - Operation of Fire protection
systems**

**15109 - Maintenance of the ship and
equipment**

Description

The purpose of this regulation is to suppress and swiftly extinguish a fire in the space of origin. For thus purpose, the following functional requirements shall be met: Fire extinguishing appliances shall be readily available. Water mist valve was closed and the engine room operating in a periodically unmanned status. Additionally, placarding next to the valve stated valve shall be locked in the open position.

The company should establish procedures to ensure that the ship is maintained in conformity with the provisions of the relevant rules and regulations and with any additional requirements which may be established by the company. The operational nature of the deficiencies noted above provide objective evidence of a serious failure of the implementation of the ISM Code. An external audit report satisfactory to the OCM I must be submitted prior to the clearance of this deficiency.