

Ship Name: **GOLDEN GRAINS**

Ship Type: **Bulk Carrier**

Flag: **Liberia**

IMO Number: **9777723**

Date of Action: **8/30/2023**

Action Taken: **Detention**

Port: **Philadelphia, Pennsylvania**

Unit: **Sector Delaware Bay**

Recognized Org: **Lloyd's Register**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers

**Reederei MS "Grainbrain II" GmbH & Co.
KG**

Deficiencies: Code - Category

11119 - Immersion suits

**15109 - Maintenance of the ship and
equipment**

Description

Before the ship leaves port and at all times during the voyage, all lifesaving appliances shall be in working order and ready for immediate use. 14 of 31 immersion suits found to have zipper liner separation at glue seams.

The company should establish procedures to ensure that the ship is maintained in conformity with the provisions of the relevant rules and regulations and with any additional requirements which may be established by the company. Company does not does not have procedures in place for the inspection of crew's immersion suites. Vessel is required to conduct ISM audit prior to departure from port.