Ship Name: PACIFIC INNOVATION

Ship Type: General Dry Cargo Ship

Flag: Liberia

IMO Number: 9469778

Date of Action: 2/19/2025

Action Taken: **Detention**

Port: Seattle, Washington

Unit: Sector Puget Sound

Recognized Org: Det Norske Veritas

Recognized Security Organization (RSO):

Recognized Org (RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related

to Detention:

Ship Management: Owners, Operators, or Managers

Nordic MPP Shipowning I AS

Nordic Hamburg Turkey Gemi Yonetim

Danismanligi AS

Deficiencies: Code - Category

> 07114 - Remote Means of control (opening,pumps,ventila

Description

Oil fuel pipes, which, if damaged, would allow oil to escape from a storage, settling or daily service tank having a capacity of 500L and above situated above the double bottom, shall be fitted with a cock or valve directly on the tank capable of being closed from a safe position outside the space concerned in the event of a fire occurring in the space in which such tanks are situated. Remote Fuel shutoff to Emergency Diesel Generator was not operational from outside the space, preventing the securing of a fuel source in the event of a fire.

This deficiency is not RO related.

07105 - Fire doors/openings in fireresisting division

Doors fitted in boundary bulkheads of machinery spaces of category A shall be reasonably gas tight and selfclosing. Doors 011 and 002 leading to stairwells and escape trunks in the engine room boundary were found out of alignment preventing full closure and increasing risk of fire spread outside of the category A machinery space.

This deficiency is not RO related.

15109 - Maintenance of the ship and equipment

Deficiencies identified by the PSCO and Flag State Control issued 18-Feb-2025 indicate a serious failure, or lack of effectiveness, of the implementation of the ISM Code. An external safety management audit has to be carried out before the ship may be released from detention.

This deficiency is not RO related.