

Ship Name: **VIKING STAR**

Ship Type: **Passenger Ship**

Flag: **Norway**

IMO Number: **9650418**

Date of Action: **9/4/2023**

Action Taken: **Detention**

Port: **Staten Island, New York**

Unit: **Sector New York**

Recognized Org: **Lloyd's Register**

Recognized Security  
Organization (RSO):

Recognized Org  
(RO) Related: **Class Related**

Relevant Certificates: **Safety Management Certificate**

Organization Related  
to Detention: **Lloyd's Register**

Ship Management: Owners, Operators, or Managers  
**Viking Ocean Cruises Ship I Ltd**  
**Wilhelmsen Ship Management (Norway) AS**

Deficiencies: Code - Category

**15109 - Maintenance of the ship and  
equipment**

**07109 - Fixed fire extinguishing  
installation**

Description

**In meeting these requirements, the company should ensure that appropriate corrective action is taken. Technician report from routine annual servicing of equipment, dated 19 Feb 2023, identified improperly connected water mist piping resulting in failures of the system to properly operate. No corrective action has been taken or planned and no reports of non-conformities were made as required by vessel's SMS. AN external ISM audit is required.**

**Fire fighting systems and appliances shall be kept in good working order and readily available for immediate use. During test of ultra-fog system in fwd and aft purifier spaces, PSCOs observed the failure of 3 of 10 ultra-fog nozzles in the fwd purifier space and the failure of 6 of 8 nozzles in the aft purifier space.**