Ship Name: MARMARIS-M Recognized Org: American Bureau of Shipping

Ship Type: **Bulk Carrier**Recognized Security
Organization (RSO)

Flag: **Panama** Organization (RSO):

IMO Number: 9450791 Recognized Org (RO) Related: Not Class Related

Date of Action: 4/25/2024 Relevant Certificates:

Action Taken: **Detention**

Port: San Juan, Puerto Rico Organization Related to Detention:

Unit: Sector San Juan

Ship Management: Owners, Operators, or Managers

Marmaris Shipping Ltd

SYNERGY SHIP MANEGMENT TURKIYE

PTE. LTD.

Deficiencies: Code - Category

15109 - Maintenance of the ship and

equipment

Description

The company and the ship shall comply with the requirements of the International Safety Management

Code. For the purpose of this regulation the

requirements of the Code shall be treated as mandatory. The company should establish procedures to ensure that the ship is maintained in accordance with the provisions of the relevant rules and regulations established by the company. The technical and/or operational nature of the deficiencies noted below provide objective evidence of a serious failure of the implementation of the ISM Code. An external ISM audit report, satisfactory to the Coast Guard, must be submitted prior to clearance of this

deficiency.

07106 - Fire detection and alarm system

The following fire detection systems shall be kept in good order so as to ensure their required performance if a fire occurs. The following smoke detectors did not activate upon initial testing: two in the oil purifier space, two in the engine control room, one above the main engine, and one above the #1 main diesel generator (6 out of 31).

30ABC Detained

07114 - Remote Means of control (opening,pumps,ventila

Oil fuel pipes shall be fitted with a cock or valve directly on the tank capable of being closed from a safe position outside the space concerned in the event of a fire. Fuel oil supply pipes to the #1 and #2 main diesel generator's quick closing devices did not fully close when activated.