

Ship Name: **MSC POLARIS**

Ship Type: **Containership**

Flag: **Liberia**

IMO Number: **9074042**

Date of Action: **4/9/2024**

Action Taken: **Detention**

Port: **Savannah, Georgia**

Unit: **Marine Safety Unit Savannah**

Recognized Org: **Bureau Veritas**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers
MSC Shipmanagement Ltd
Messina Marine Ltd

Deficiencies: Code - Category

**15111 - Company verification,
review and evaluation**

**07109 - Fixed fire extinguishing
installation**

Description

The company should establish procedures to ensure the ship is maintained in accordance with the provisions relevant to the rules and regulations established by the company. The technical and/or operational nature of deficiencies 02, 03, and 04 provide objective evidence of the serious failure to implement the ISM Code. Prior to the OCMI clearance of these deficiencies, an external audit report must be submitted to this office.

After any survey of the ship, no change shall be made in the structural arrangements, machinery, equipment and other items covered by the survey without the sanction of the Administration. PSCO observed unapproved modifications to the fire main piping system within the reefer control store which which is in direct conflict with fire control plan.