

Ship Name: **MARCO VI**

Ship Type: **Ro-Ro-Cargo Ship**

Flag: **Togo**

IMO Number: **7047203**

Date of Action: **8/20/2024**

Action Taken: **Detention**

Port: **St. Thomas, USVI**

Unit: **Marine Safety Unit St. Thomas**

Recognized Org: **CONARINA**

Recognized Security  
Organization (RSO):

Recognized Org  
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related  
to Detention:

Ship Management: Owners, Operators, or Managers

**Marco Marine LLC**

**Marco St Croix Inc**

Deficiencies: Code - Category

**01214 - Endorsement by flagstate**

**15109 - Maintenance of the ship and  
equipment**

Description

**The endorsement required by Article VI of the Convention to attest the issue of a certificate shall only be issued if all the requirements of the Convention have been complied with. Second engineer could not provide Flag State endorsements for their national certificates since arrival on vessel on 18JUL2024.**

**The company should establish procedures to ensure that the ship is maintained in conformity with the provisions of the relevant rules and regulations and with any additional requirements which may be established by the company. The technical and/or operational nature of deficiencies 02, 03, 04, 05, 06, and 08 provide objective evidence of a serious failure of the implementation of the ISM Code. A third-party Safety Management System audit must be conducted and a report, satisfactory to the OCMI, must be submitted prior to clearance of this deficiency. 74 SOLAS (2020) IX/3.1 ISM Code 10.1**