

Ship Name: **NV ATHENA**

Ship Type: **Chemical Tankship**

Flag: **Singapore**

IMO Number: **9527075**

Date of Action: **1/17/2025**

Action Taken: **Detention**

Port: **Lake Charles, Louisiana**

Unit: **Marine Safety Unit Lake Charles**

Recognized Org: **Nippon Kaiji Kyokai**

Recognized Security  
Organization (RSO):

Recognized Org  
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related  
to Detention:

Ship Management: Owners, Operators, or Managers

**Nhat Viet Transportation Corporation**

**Yong Sheng Shipping Pte Ltd**

Deficiencies: Code - Category

**02110 - Beams, frames, floors-  
op.damage**

**15110 - Documentation-ISM**

Description

**Whenever an accident occurs to the ship or a defect is discovered, either of which effect the safety of the ship, the master or owner of the ship shall report at the earliest opportunity to the administration, the nominated surveyor or recognized organization responsible for issuing the relevant certificate, who shall cause investigations to be initiated to determine whether a survey as required by regulation 7, 8, 9, 10 is necessary. While investigating the failure of the 5S cargo tank unreported previous repairs were identified to the 10P and 10S cargo/slop tanks. Crew logged repairs to the 10P and 10S cargo tanks in the hot work log on board the ship but no reports could be found to class or flag at this time. Cargo tanks are identified as a critical item. A report by class is required to ascertain the safety of the tanks and repairs that were made.**

**Objective evidence discovered in an expanded ISM exam following a reportable casualty revealed the following major nonconformity; the vessel failed to fully implement the requirements of the SMS as evident by deficiency #01. An external audit is required.**