

Ship Name: **WAN CHENG**

Ship Type: **Chemical Tankship**

Flag: **Liberia**

IMO Number: **9234587**

Date of Action: **1/10/2025**

Action Taken: **Detention**

Port: **New Orleans, Louisiana**

Unit: **Sector New Orleans**

Recognized Org: **Lloyd's Register**

Recognized Security
Organization (RSO):

Recognized Org
(RO) Related: **Not Class Related**

Relevant Certificates:

Organization Related
to Detention:

Ship Management: Owners, Operators, or Managers

Lisbon Shipping Limited

Wancheng Shipping Ltd

Deficiencies: Code - Category

**07106 - Fire detection and alarm
system**

**15109 - Maintenance of the ship and
equipment**

Description

Any required fixed fire detection and fire alarms system with manually operated call points shall be capable of immediate operation at all times. PSCO observed several smoke and flame detectors to be covered with either rags or plastic coverings rendering them unable to operate as intended. Areas concerned were over No.1 Auxiliary Engine, engineer's workshop, and steering gear room.

The company and the ship shall comply with the requirements of the International Safety Management Code. The company should establish procedures to ensure that the ship is maintained in conformity with the provisions of the relevant rules and regulations and with any additional requirements which may be established by the Company. The technical and/or operational nature of the deficiencies 01 and 02 provide objective evidence of a serious failure of the implementation of the ISM Code. An external audit report satisfactory to the OCMI must be submitted prior to clearance of this deficiency.